

Person Performing Inspection

Octavio Covian

Additional Employees

Customer Name

Morning Star, Los Banos

Job#

5540

Date

2024-04-05 00:00:00

Task To Be Done This Shift

Hazard Associated With Task

slips, trips, falls, electrical hazards

Ideas To Reduce Risk

proper ppe

PPE For Task

Harness, satey glasses, saftey gloves

Truck/Equipment Number

skyjack II2553NF

Gauges

OK 

Tires/Tracks

OK 

Emergency Brake

N/A 

Fire Extinguisher

N/A 

Back Up Alarm

N/A 

Lights

OK 

Oil Level

OK 

Coolant Level

N/A 

Hyd. Fluid Level

OK 

Seat Belt

N/A 

Wipers/Windshield

N/A 

Horn

OK 

Safety Switches

OK 

Emergency Control

OK 

Description Of Repairs Needed

Any Other Items Not Mentioned That May Be Defective

Truck/Equipment Number

Truck 36

Gauges

OK 

Tires/Tracks

OK 

Emergency Brake

N/A 

Fire Extinguisher

N/A 

Back Up Alarm

N/A 

Lights

OK 

Oil Level

OK 

Coolant Level

N/A 

Hyd. Fluid Level

OK 

Seat Belt

N/A 

Wipers/Windshield

N/A 

Horn

OK 

Safety Switches

OK 

Emergency Control

OK 

Description Of Repairs Needed

Any Other Items Not Mentioned That May Be Defective