

Person Performing Inspection

eric g

Additional Employees

Octavio Covian
Daniel iniguez
Tadeo Fernandez
Chad Pattee
david gonzalez
anthony alves
scott mchale

Customer Name

mm merced

Work Area

5629

Date

2024-09-30 / 05:28 AM

Task To Be Done This Shift

continue building out mcc
conduit runs on crushers
prepping for concrete

Hazard Associated With Task

open trench
heat
cuts scrapes
slips trips falls

Ideas To Reduce Risk















ppe
jha
caution tape and markers

PPE For Task

hardhat
boots
hi vis
gloves
glasses

Truck/Equipment Number

23















Gauges	Tires	Emergency Brake	Fire Extinguisher	Backup Alarm
OK 	OK 	OK 	OK 	OK 
Lights	Oil Level	Coolant Level	Hyd Fluid Level	Seat Belt
OK 	BAD 	BAD 	BAD 	OK 
Wipers	Horn	Safety Switches	Emergency Control	
OK 	OK 	N/A 	N/A 	

Description Of Repairs Needed

Any Other Items Not Mentioned That May Be Defective

Truck/Equipment Number

29















Gauges	Tires	Emergency Brake	Fire Extinguisher	Backup Alarm
OK 	OK 	OK 	OK 	OK 
Lights	Oil Level	Coolant Level	Hyd Fluid Level	Seat Belt
OK 	OK 	OK 	OK 	OK 
Wipers	Horn	Safety Switches	Emergency Control	
OK 	OK 	N/A 	N/A 	

Description Of Repairs Needed

Any Other Items Not Mentioned That May Be Defective

Truck/Equipment Number

40











Gauges	Tires	Emergency Brake	Fire Extinguisher	Backup Alarm
OK 	OK 	OK 	OK 	OK 
Lights	Oil Level	Coolant Level	Hyd Fluid Level	Seat Belt
OK 	OK 	OK 	OK 	OK 
Wipers	Horn	Safety Switches	Emergency Control	
OK 	OK 	N/A 	N/A 	

Description Of Repairs Needed

Any Other Items Not Mentioned That May Be Defective

Truck/Equipment Number

red manlift

Gauges	Tires	Emergency Brake	Fire Extinguisher	Backup Alarm
OK 	OK 	N/A 	OK 	OK 
Lights	Oil Level	Coolant Level	Hyd Fluid Level	Seat Belt
OK 	OK 	OK 	OK 	OK 
Wipers	Horn	Safety Switches	Emergency Control	

